RIPON AREA SCHOOL DISTRICT Community Engagement Session Thursday, September 19, 2013

PRE-SCHOOL & PRIMARY LEVEL

STRENGTHS	WEAKNESSES
GENERAL COMMENTS	GENERAL COMMENTS
Community Based Collaborative Models	Pre-School & Primary Not in One School
Community based Collaborative Models	Security Not Consistent Between Schools
	Too Many Pre-School Sites
	Poor Ventilation & Temperature Control
	Lack of Awareness of All Positives in District
BARLOW PARK/JOURNEY ELEMENTARY SCHOOL	BARLOW PARK/JOURNEY ELEMENTARY SCHOOL
Air Conditioning	Lockers/Daily Storage;
	Sufficient for Winter Gear?
Property for Growth	Halls are Chaos at Arrival/Departure
Lots of Land	Not Enough Event Space and Parking;
	Even at Pick-Up Time
Large Lot Size	Cafetorium = Cafeteria/Auditorium;
	Too Small for Functions
Newer Facility; Appealing Aesthetically	Gym No Room to Grow for Adding More Active Programs
New Facility	Building Security Minimal; Could Be Improved
New Facility; Security On One Level	Site Tight at Drop-Off/Pick-Up;
New Facility, Security Off Offe Level	Poor Traffic Flow
Near High School and Middle School	Parking and Pick-Up/Drop Off Congestion Problem
Ability to Separate Age Groups	One Way In/One Way Out; Traffic Issues
Room to Grow on Current Grounds	, , , , ,
	Not Enough Event Parking Bad Traffic Flow; Too Congested Before School; Use Barlow
Nice Playground Area	Park for Some Traffic;
	Morning Drop-Off Worse
Many After School Activities;	Parking/Drop Off Not Conducive to How It Is Actually Used;
·	Some Drop, Kiss and Fly While Others Walk Their Kids;
Well Planned for Space Available	Commotion Mixed Use
Nowast School/Frash Dasign	Location; Near Many Busy Streets; Difficult for Small
Newest School/Fresh Design	Children to Walk Safely to School
Newest School in District	Cafeteria Too Small When Used as Auditorium
Good Serving Kitchen; Serving Line Layout	Barlow, Middle and High Have Traffic Flow Down
Good Serving Ritchell, Serving Line Layout	Metomen St; Traffic Nightmare Before/After School
Location of School	Roof and Windows Leak
Location of School	Building Security – Lake of Office Security
RIPON CHILDREN'S LEARNING CENTER	RIPON CHILDREN'S LEARNING CENTER
Good Location; Large Play Area;	Security Non-Existent
Easy to Get Students to School	Security Non-Existent
Decent Busing Plan;	Parking Too Small; Difficult to Get In/Out
Coordination with District Programs	Tarking 100 smail, Difficult to Get III/ Out
Coordination with District Flograms	Old Site; No Security
PICKET COMMUNITY CENTER	PICKET COMMUNITY CENTER
. 16.12.1 66.11.11.1 62.11.2.1	Security Non-Existent
	Building Not Handicap Accessible
	Old Site; No Security
	Very Old Facility
	Transportation a Problem
	Transportation a Problem Travel Time
ADVOCAP/HEAD START	ADVOCAP/HEAD START
ADVOCAT/ NEAD START	Old Facility; Very Out Dated
	Way Out Yonder; No Connection to Main District Travel Time
	Old Facility; Very Out-Dated